	DBs	3	Time St	amp	Comments	Error Definition
1	US-PGPUB; US USOCR	SPAT;	2007/05/22	15:21		
2	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:23		
3	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:25		
4	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:25	-	
5	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:28		
6	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:29		
7	US-PGPUB; US USOCR	SPAT;	2007/05/31	12:00		
8	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:42		
9	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:28		
10	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:46		
11	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:49		
12	US-PGPUB; US USOCR	SPAT;	2007/05/21	12:07		
13	US-PGPUB; US USOCR	SPAT;	2007/05/21	10:02		
14	US-PGPUB; US USOCR	SPAT;	2007/05/21	09:58	,	
15	US-PGPUB; US USOCR	SPAT;	2007/05/21	11:18		
16	US-PGPUB; US USOCR	SPAT;	2007/05/21	11:19		
17	US-PGPUB; US USOCR	SPAT;	2007/05/21	11:19		
18	US-PGPUB; US USOCR	SPAT;	2007/05/21	11:19		
19	US-PGPUB; US USOCR	SPAT;	2007/05/21	11:23		
20	US-PGPUB; US USOCR	SPAT;	2007/05/21	11:23		
21	US-PGPUB; US USOCR	SPAT;	2007/05/21	11:30		

	Туре	Ref #	Hits	Search Text	
1	BRS	S1	0	"10775714"	
2	IS&R	S2	О	("10775714").PN.	
3	BRS	S3	3	(controlling ADJ moisture) AND (straw ADJ bale)	
4	BRS	S4	822	52/302.1.ccls.	
5	BRS	S5	4	52/302.1.ccls. AND (straw ADJ bale)	
6	BRS	S7	3	52/302.1.ccls. AND (straw AND concrete)	
7	BRS	S8	0	52/302.1.ccls. AND (straw ADJ wall)	
8	BRS	S9	123	(straw ADJ bale) AND wall	
9	BRS	S6	0	52/302.1.ccls. AND (straw NEAR concrete)	
10	BRS	S10	21	(straw ADJ bale) AND wall AND foundation	
11	BRS	S11	575	(hay ADJ bale) AND wall	
12	IS&R	S13	1	("6061986").PN.	
13	IS&R	S14	1	("5605416").PN.	
14	BRS	S12	22	(hay ADJ bale) AND wall AND foundation	
15	IS&R	S15	0	("stepANDfoundationANDbelow").PN.	
16	BRS	S16	576 <u>8</u> 8	step AND foundation AND below	
17	BRS	S18	0	step SAME foundation AND below AND "52".ccls.	
18	BRS	S17	6323	step SAME foundation AND below	
19	BRS	S20	6270	open AND foundation AND moisture	
20	BRS	S19	3332	step SAME foundation AND below AND "52"	
21	BRS	S21	991	open AND foundation AND moisture AND drain	

	Туре	Ref #	Hits	Search Text		
22	BRS	S22	9	(hay ADJ bale) AND wall AND runner		
23	BRS	S23	22	(hay ADJ bale) AND wall AND foundation		
24	BRS	S24	3	(straw ADJ bale) AND wall AND runner		
25	BRS	S25	21	(straw ADJ bale) AND wall AND foundation		
26	IS&R	S26	0	("(bondADJbeam)ANDairANDplenum").PN.		
27	BRS	S27	0	(bond ADJ beam) AND air AND plenum		
28	BRS	S28	74	(bond ADJ beam) AND air AND wall		
29	BRS	S29	10	(bond ADJ beam) AND straw		
30	BRS	S30	3	(bond ADJ beam) AND airspace .		
31	BRS	S33	431	plenum AND straw		
32	BRS	S31	4	(straw ADJ bale) AND attic		
33	BRS	S32	79715	plenum		
34	BRS	S34	30	plenum AND straw AND roof		
35	IS&R	S35	1	("6796100").PN.		
36	IS&R	S36	0	("undergroundANDfoundationANDvent").PN		
37	BRS	S37	441	underground AND foundation AND vent		
38	BRS	S38		underground AND foundation AND vent AND moisture		
39	BRS	S39	2	((U ADJ shaped) NEAR galvanized) AND plenum		
40	IS&R	S40	1	("5937588").PN.		
41	BRS	S41	22	52/309.12.ccls. AND ventilation		
42	BRS	S45	454	"454" AND plenum AND ventilation		

	DBs	Time Stamp	Comments	Error Definition
22	US-PGPUB; USPAT; USOCR	2007/05/21 11:31		
23	US-PGPUB; USPAT; USOCR	2007/05/31 12:13		
24	US-PGPUB; USPAT; USOCR	2007/05/21 11:32		·
25	US-PGPUB; USPAT; USOCR	2007/05/21 11:32		
26	US-PGPUB; USPAT; USOCR	2007/05/21 12:08		
27	US-PGPUB; USPAT; USOCR	2007/05/21 12:08		
28	US-PGPUB; USPAT; USOCR	2007/05/21 12:12		
29	US-PGPUB; USPAT; USOCR	2007/05/21 12:14		
30	US-PGPUB; USPAT; USOCR	2007/05/21 12:45		,
31	US-PGPUB; USPAT; USOCR	2007/05/21 15:04		
32	ปร-PGPUB; USPAT; USOCR	2007/05/21 15:03		
33	US-PGPUB; USPAT; USOCR	2007/05/21 15:03		
34	US-PGPUB; USPAT; USOCR	2007/05/21 15:29		
35	US-PGPUB; USPAT; USOCR	2007/05/21 15:54		
36	US-PGPUB; USPAT; USOCR	2007/05/21 15:54		
37	US-PGPUB; USPAT; USOCR	2007/05/21 15:56		
38	US-PGPUB; USPAT; USOCR	2007/05/21 16:02		
39	US-PGPUB; USPAT; USOCR	2007/05/21 16:03		
40	US-PGPUB; USPAT; USOCR	2007/05/22 16:29		
41	US-PGPUB; USPAT; USOCR	2007/05/22 16:37		
42	US-PGPUB; USPAT; USOCR	2007/05/22 16:41		

	Туре	Ref #	Hits	Search Text	
43	BRS	S42	2	52/309.12.ccls. AND plenum	
44	BRS	S43	o	"454".ccls. AND plenum	
45	BRS	S44	6606	"454" AND plenum	
46	BRS	S46	24	ventilation AND straw AND plenum	
47	IS&R	S47	1	("6494006").PN.	
48	IS&R	S48	0	("(StrawADJbale)ANDladder").PN.	
49	BRS	S49	2	(Straw ADJ bale) AND ladder	
50	BRS	S50	123	(Straw ADJ bale) AND wall	
51	BRS	S51	6	52/302.1.ccls. AND (straw AND wall)	
52	BRS	S52	575	(hay ADJ bale) AND wall	
53	BRS	S53	55	(hay ADJ bale) AND wall AND building	
54	BRS	S54	99	Rainbolt	
55	BRS	S55	200	wall ADJ bracing AND system	

	DBs	Time Stamp	Comments	Error Definition
43	US-PGPUB; USPAT; USOCR	2007/05/22 16:39		
44	US-PGPUB; USPAT; USOCR	2007/05/22 16:39		
45	US-PGPUB; USPAT; USOCR	2007/05/22 16:44		
46	US-PGPUB; USPAT; USOCR	2007/05/22 17:34		
47	US-PGPUB; USPAT; USOCR	2007/05/22 17:35		
48	US-PGPUB; USPAT; USOCR	2007/05/31 11:52		
49	US-PGPUB; USPAT; USOCR	2007/05/31 11:52		
50	US-PGPUB; USPAT; USOCR	2007/05/31 11:52		
51	US-PGPUB; USPAT; USOCR	2007/05/31 12:01		
152	US-PGPUB; USPAT; USOCR	2007/05/31 12:05		
13.3	US-PGPUB; USPAT; USOCR	2007/05/31 12:05		
154	US-PGPUB; USPAT; USOCR	2007/05/31 12:22		
55	US-PGPUB; USPAT; USOCR	2007/05/31 12:22		